

~~SECRET~~**PRIORITY**

Declassification Review by NGA/DoD

P 201700Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUCVAB/4080 STRAT WG, OL 19, BARKSDALE AFB, LA

RUCVAB/2D RTS, BARKSDALE AFB, LA

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUWBKG/15TT AF, MARCH AFB, MARCH AFB, RIVERSIDE, CALIF

RUWGAA/2AF, BARKSDALE AFB, LA

DA GRNC

BT

~~SECRET~~

CITE CIA-Z-1024

15TH AF (FOR DI); SAC (FOR DIM, BRASS KNOB, DOCR, DM 4) 2D AF
(FOR DI). FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER.

1. CAMERA B 8 WAS USED IN MISSION 3773 FLOWN ON 15 NOVEMBER
1963; PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

HFS
CJS
GFC
PMS
AEL

Grace (File)

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: TWO STAINS THAT APPEAR TO HAVE BEEN CAUSED BY
OXIDIZED DEVELOPER APPEAR ON FRAME 1707. THERE IS A MANUFACTURING
SPlice ON FRAME 495 WITH ASSOCIATED PLUS AND MINUS DENSITY STREAKS
IN FRAMES 494 AND 495 AND A HEAVY CREASE EXTENDING TO FRAME 521.
EMULSION BLISTERS ARE NUMEROUS THROUGHOUT THE MISSION.

(EXAMPLE FRAME 982).

C. 9L SIDE: MINUS DENSITY DOTS ARE MINOR BUT NUMEROUS ON
THE FIRST 130 FRAMES. CREASES ON FRAMES 162 THROUGH 167 ARE
ASSOCIATED WITH A MANUFACTURING SPlice ON FRAME 161. FRAMES
596-599 ARE AFFECTED BY CREASES WHICH ARE ASSOCIATED WITH A
MANUFACTURING SPlice ON FRAME 595. DRYING MARKS AND RANDOM,
MINOR CREASES APPEAR ON FRAMES 1430 THROUGH 1451.

~~SECRET~~

GROUP 1
Excluded from automatic
downgrading and
declassification

THERE IS A FOGGED AREA 2" WIDE, PARALLEL TO THE MINOR AXIS, ON THE TRAILING EDGE OF FRAME 1775.

D. BOTH SIDES: EDGE FOG IS INTERMITTENT ON BOTH EDGES. PROCESSING STREAKS ARE CONTINUOUS THROUGHOUT THE MISSION. THERE ARE 2064 FRAMES ON EACH SIDE OF THIS MISSION.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING ANOMALIES.

3. POSITIVE:

A. PRINTING AND PROCESSING WERE GOOD.

B. PI SUITABILITY IS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 55 PERCENT OF THIS MISSION.

S E C R E T

END OF MESSAGE

1